Strapping Slots for BR-MPM2 & Installing with Accessory BR-MPM2-AC Kit

BR-MPM2: Bare Mount
KT-CDR2: 1 Integrated Power Supply
KT-CDR3: 2 Integrated Power Supplies

When Bracket is used alone, ½" wide stainless strapping can be used either image 1) on center slots for smaller dia. poles, or image 2) on side slots


Image 1) Center Slots for strapping
Start strapping from rear, this view show slot arrows shown on face

Image 2) Side Slots for Strapping
Start strapping from rear, this view shows slot arrows from rear view

BR-MPM2-AC (Accessory Sold Separately)
Strap slots indicated by arrows

BR-MPM2-AC mates & nests into rear of BR-MPM2 bracket

Strapping is threaded from rear thru slots indicated. Face view shown

When BR-MPM2-AC is Used, sides have ¼"-20 threaded Inserts to mate to BR-MPM2, Use 6 bolts provided to mate. Use center strapping slots for pole mounting

Assembly mated for pole mounting
(Fasteners not shown)

Assembly reverse mated for wall mounting, or use with pole or parapet mount